

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	3	"6506103".pn.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:09
L2	68683	(remov\$3) near25 (conductiv\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:10
L3	527	(remov\$3) near25 (conductiv\$3) near25 (electrochemical\$3)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:11
L4	151	((remov\$3) near25 (conductiv\$3) near25 (electrochemical\$3)) near35 (electrode or voltage)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:48
L5	47	4 and (excess or overburden)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:12
L6	454	((remov\$3) near25 (material\$1) near25 (electrochemical\$3)) near35 (electrode or voltage)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:49
L7	304	((remov\$3) near5 (material\$1) near25 (electrochemical\$3)) near35 (electrode or voltage)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:53
L8	168169	"438"/\$.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:49
L9	13	7 and 8	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:50

L10	0	7 and (porous near3 memeber)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:53
L11	5	7 and (porous near3 member)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 14:57
L12	95	7 and (porous)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:19
L13	12064	(porous near2 member)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:19
L14	62	((porous near2 member)) near15 (conductive near material)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:25
L15	1	((porous near2 member)) near15 ((overburden or excee) near3 (conductive near material))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:21
L16	1	((porous near2 member)) near15 ((overburden or excess) near3 (conductive near material))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:21
L17	1	((porous near2 member)) near15 ((overburden or excess) near3 (conductive near5 material))	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:21
L18	11	14 and (overburden or excess)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:22
L19	2563	((porous)) near15 (conductive near material)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:25

L20	177	19 and (remov\$3) near10 (overburden or excess)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:26
L21	148	19 and (remov\$3) near5 (overburden or excess)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:26
L22	2	19 and (remov\$3) near5 (overburden)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:27
L23	148	19 and (remov\$3) near5 (excess)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:27
L24	95	19 and (remov\$3) near (excess)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:27
L25	30	19 and ((remov\$3) near (excess)) near4 (material)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2005/06/22 15:28